



Subject: Turn Signals Engage When Depressing the Brake Pedal
Models Years Affected: 2017 - SOP to H1129315
Models Affected: Chevrolet Express/GMC Savana Cut-away Vans with Separated Rear Stop/Turn Signals (V4D)
Origination Date: October 17, 2016
Revision Date: October 27, 2016

ADVISORY:

This UI Bulletin is being created using information contained in General Motors Preliminary Information Bulletin 16-NA-345 V2

Condition/Concern:

Some customers may comment that the turn signals engage when pressing on the brake pedal.

Cause:

This condition may be caused by a software anomaly.

Correction:

- For vehicles without UY7, update the body control module (BCM) with the latest software. Refer to *Body Control Module Programming and Setup in SI*.
- **DO NOT** perform this bulletin on vehicles with UY7 RPO. This change will result in the loss of stop lamp functionality for the trailer lamps if performed. Engineering is developing a solution for these vehicles.

Note: The solution will not be a SW solution. The UY7 (trailer capability) will either need to be removed or the vehicle will need to be rewired to retain proper trailering operation.

Warranty Information:

Dealers should refer to Bulletin 16-NA-345 for applicable warranty labor operation and time

General Motors Upfitter Integration

<http://www.gmupfitter.com>