UI Bulletin #154









Upfit Body Mounting / Chassis Wiring Harness Subject:

Routing

Chevrolet Silverado/GMC Sierra 3500 HD Models:

Cab Chassis Models only

Model Years: 2011 and Beyond

Date: July 19, 2019

Revision Date N/A

ADVISORY:

This GM UI Bulletin is designed to assist upfitters with upfit body to frame interface regarding the rear chassis wiring harness on C/K HD Cab Chassis models

Condition/Concern:

Care must be taken when installing upfit bodies on the rear driver's side chassis to allow clearance to wiring harness/attachments. Wiring Harness `Service Access' could be compromised when mounting an upfit body. Upfit Body mounting provisions should not pinch or lock in the OEM harness/attachments.




Figure 1 Harness Area of Concern

General Motors Upfitter Integration

http://www.gmupfitter.com

General Motors Upfitter Integration

UI Bulletin #154









Recommendation:

Upfit body mounting practices and provisions should allow for service of chassis wiring harness/attachments.

If the upfitter chooses to relocate the harness inboard, they're responsible for the proper securing and protection of the harness. Similar OEM harness support intervals should also be utilized. Care should be taken so harness does not chafe sensitive chassis lines, components and modules.

Additional Information:

Refer to GM UI BEST PRACTICES `CHASSIS' & `ELECTRICAL' Sections regarding serviceability, routing and securing chassis wiring harnesses. http://www.gmupfitter.com

General Motors Upfitter Integration

http://www.gmupfitter.com