

**Subject:** Fuel Cap Tether Strap

**Models:** Chevrolet Express/GMC Savana  
Cutaways with a service body installed

**Model Years:** 2012 and beyond

**Date:** December 13, 2012

**Revision** June 6, 2014

**Date:**

## ADVISORY:

This UI Bulletin is being created using information contained in General Motors Technical Bulletin PI0837


This bulletin was updated to include model years beyond 2012

### Condition/Concern:

A condition may be caused by the fuel cap tether binding when installing the fuel cap and not allowing the fuel cap to seal completely or by the fuel cap tether being trapped between the fuel cap seal and the fuel fill pipe, not allowing the fuel cap to seal completely, possibly resulting in a Service Engine Soon Light being illuminated.


### Repair/Recommendation:

To avoid the above noted condition, all vehicles with a service body installed and using a stainless steel tethered fuel cap (9B4) should tether the cap as shown below.



This

verses



Not This

**General Motors Upfitter Integration**

<http://www.gmupfitter.com> • 1-800-875-4742 (Upfitter Hotline)