



UI Bulletin #191

Subject: Cautionary – NO Drill/Air Bag Zones – Zevo Cargo Van
Models Affected: Bright Drop Zevo Cargo Vans
Models Years Affected: 2022 and beyond
Origination Date: May 3, 2023
Revision Date: N/A

ADVISORY:


NOTE: The information in this bulletin as it pertains to the zoning areas is for general reference only. If precise location or area definitions are needed for the purposes of designing or mounting of upfit equipment or components a Math Data request is required.

Concern:

Upfitters need the locational information for the air bag deployment and the NO DRILL zones for the purposes of installing equipment.

Recommendation:


Air Bag Deploy Zones:




General Motors Upfitter Integration
<http://www.gmupfitter.com>



Driver Air Bag



Side Impact & Roof Rail Air Bags






UI Bulletin #191

NO Drill Zones

MY22 FWD




	Airbag		Stored gas inflator		Seat belt pretensioner		SRS control unit		Pedestrian protection active system
	Automatic rollover protection system		Gas strut/Preloaded spring		High strength zone		Zone requiring special attention		
	Battery low voltage		Ultra capacitor, low voltage		Fuel tank		Gas tank		Safety valve
	High voltage battery pack		High voltage power cable component		High voltage disconnect		Fuse box disabling high voltage system		Ultra capacitor, high voltage

DO NOT CUT ANY ORANGE COLORED HIGH VOLTAGE CABLES	Identification Number	Version Number	Page Number
	5G5-21101	1	1

Disclaimer: GM Upfitter Integration Technical Bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service and/or modification of a vehicle. These properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. Contact GM Upfitter Integration for information on whether the information is applicable your vehicle.



MY23 AWD



MY23 AWD

- Underbody content:
 - HV Battery (orange)
 - HV Cables/Modules/Drive Units (orange)
 - 12V Wiring (green)
 - Brake Lines (red)
 - HVAC Plumbing (Pink)

No drilling above HV Battery
No cutting of orange HV cables
No modifications to HVAC Plumbing

DC Charging Manual Release Cable



HV Battery

Charge Port

GENERA



UI Bulletin #191

<h3>SRS Airbag Module & Impact Sensors</h3> <ul style="list-style-type: none">• SRS Airbag module centrally located under Lower IP Bin• 6 Impact Sensors 	<h3>Security Access Antennas</h3> <ul style="list-style-type: none">• 8 Key Fob Antennas• Covering antennas will impair keyless entry/exit performance• Keyed lock access at rear door 
---	---

Additional Information:

As noted at the start of this document this information is reference only...it is not scale nor can be used in the design or developed of any after-market or upfitter equipment. For accurate dimensional and locational information a request for Math Data (CAD) should be submitted to GM Upfitter Integration via the contact us form.

<https://www.gmupfitter.com/contact/>

006X

Disclaimer: GM Upfitter Integration Technical Bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service and/or modification of a vehicle. These properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. Contact GM Upfitter Integration for information on whether the information is applicable your vehicle.