





UI Bulletin #187

Subject: Adding Equipment to Vehicles with Air Bags

(SIR) and Other Vehicle/Passenger Safety

Systems.

Models Affected:

All passenger, Light and Medium Duty Trucks

Models Years

2018 - Present

Affected: Origination

Date:

June 22, 2022

Revision

N/A Date:

ADVISORY:

Condition/Concern:

Upfitter/Customer have from time to time have added electrical equipment and have unknowingly tapped into or altered the power provisions to some critical safety systems, including but limited to the Sensing and Diagnostic Module (air bag). It is **IMPORTANT** that the power to these safety system control modules not be used or modified as doing so may result in a loss of function during the various stages of vehicle power mode. Other vehicle/passenger safety system that may also be impacted if the power provisions be modified or altered include (but not limited to) are as follows:

- Passenger Present Detection
- Tire Pressure Monitoring System (TPMS)
- Advanced Driver Assistance Systems (ADAS)

Repair/Recommendation:

Do not connect aftermarket accessories into the SIR circuits or any other vehicle/passenger safety system. All such circuits are indicated on circuit diagrams with the SIR symbol.

Additional Information:

Contact General Motors Upfitter Integration (https://www.gmupfitter.com/contact/) for addition information or assistance should you have questions or concerns regarding upfitting your vehicle.

General Motors Upfitter Integration

http://www.gmupfitter.com

Page | 1 **Bulletin #187** Date: July 12, 2022