

Subject: "HYRAIL" FGAWR Upgrade
Models Affected: Chevrolet Silverado 2500/3500
GMC Sierra 2500/3500
w/V8 Gasoline – Single Rear Wheel
Model Years: 2011 and beyond
Date: April 13, 2011
Revision Date: June 13, 2014

ADVISORY:

Condition/Concern:

The Special Equipment Option (SEO) 8W9 "HYRAIL" Front Gross Axle Weight Rating (FGAWR) Upgrade" has been carried into the 2011 C/K 2500/3500 models with single rear wheels and V/8 Gas engine. This bulletin identifies the correct Service Parts to upgrade non-SEO 8W9 20000/30000 Series Trucks to SEO 8W9 status. SEO 8W9 consists of a Front Shock and Torsion Bar upgrade increasing FGAWR on 2WD and 4WD vehicles. Service must be completed at an authorized GM Dealer or SVM.

Note: Please refer to UI Bulletin #83 for information on the Tire Pressure Monitoring System and proper sensor and calibration details.

Repair/Recommendation:

Refer to the Table on the following page for proper part numbers required to perform the HYRAIL GAWR upgrade

General Motors Upfitter Integration

<http://www.gmupfitter.com> • 1-800-875-4742 (Upfitter Hotline)

"HYRAIL" Front Gross Axle Weight Rating (FGAWR) Upgrade

MODEL	STD. FGAWR	TORSION BAR		SHOCKS (2 REQ)	UPGRADED FGAWR
		LEFT FRONT	RIGHT FRONT		
2500 HD Models w/V-8 Gasoline engine					
C20,25903	4400	20883358	20883359	20908414	4800
K20,25903	4400	20883360	20883361	20908415	5200
C20,25753	4400	20883360	20883361	20908415	5200
K20,25753	4400	20883360	20883361	20908415	5200
C20,25953	4400	20883360	20883361	20908415	5200
K20,25953	4800	20883362	20883363	20908415	5600
C20,25743	4400	20883360	20883361	20908415	5200
K20,25743	4800	20883360	20883361	20908415	5200
C20,25943	4400	20883360	20883361	20908415	5200
K20,25943	4800	20883362	20883363	20908415	5600
3500 HD Models w/V-8 Gasoline engine					
C30,35903	4400	20883358	20883359	20908414	4800
K30,35903	4400	20883362	20883363	20908415	5600
C30,35953	4400	20883360	20883361	20908415	5200
K30,35953	4800	20883362	20883363	20908415	5600
C30,35743	4400	20883360	20883361	20908415	5200
K30,35743	4800	20883362	20883363	20908415	5600
C30,35943	4400	20883360	20883361	20908415	5200
K30,35943	4800	20883362	20883363	20908415	5600

General Motors Upfitter Integration

<http://www.gmupfitter.com> • 1-800-875-4742 (Upfitter Hotline)