

Subject:Cautionary – NO Drill/Air Bag ZonesModelsSilverado EVAffected:2024 and beyondOrigination<br/>Date:July 18, 2023Revision<br/>Date:N/A

# **ADVISORY:**

NOTE: The information is this bulletin as it pretains to the zoning areas is for general reference only. If precise location or area definitions are needed for the purposes of designing or mounting of upfit equipment or components a Math Data request is required.

#### **Concern:**

Upfitters need the locational information for the air bag deployment and the NO DRILL/NO CUT zones for the purposes of installing equipment.

#### **Recommendation:**

Air Bag Deploy Zones:



#### **General Motors Upfitter Integration**

http://www.gmupfitter.com

Bulletin #195


Date: August 4, 2023




**Driver Air Bag** 



Side Impact & Roof Rail Air Bags





#### **General Motors Upfitter Integration**

http://www.gmupfitter.com


Bulletin #195

Date: August 4, 2023



### No Drill/No Cut Zones

#### MY24 FWD



#### **General Motors Upfitter Integration**


http://www.gmupfitter.com

Bulletin #195

Date: August 4, 2023



#### MY24 AWD



#### **General Motors Upfitter Integration**


http://www.gmupfitter.com

Bulletin #195

Date: August 4, 2023



## **UI Bulletin #195**



#### **Additional Information:**

As noted at the start of this document this information is reference only...it is not scale nor can be used in the design or developed of any after-market or upfitter equipment. For accurate dimensional and locational information a request for Math Data (CAD) should be submitted to GM Upfitter Integration via the contact us form.

https://www.gmupfitter.com/contact/

06X

#### **General Motors Upfitter Integration**

http://www.gmupfitter.com

Bulletin #195

Date: August 4, 2023