



® COACHBUILDER INFORMATION UPDATE

Date: March 20, 2013

Bulletin Number: XTS 17

Subject: Cadillac PV Paint on B9Q Chassis

This bulletin is to inform you of important information related to the Cadillac Professional Vehicle Incomplete B9Q Chassis.

The GM Oshawa assembly plant will be revising the current paint process on the B9Q chassis. The assembly plant will begin to eliminate the base coat and clear coat rearward of the B-Pillar.

Please review the attached file that will show an example of the new paint process for the B9Q chassis.

If you have any questions or concerns, call Joe Pennington at (248) 808-0854.